


Fig. 2






FIG. 4A




FIG. 4B





FIG. 5A



7/9




FIG. 6A




FIG. 6B

8/9

POR No Bars




FIG. 7A

POR with Bars




FIG. 7B

9/9

Bars with Hi O2




FIG. 7C

Bars with Co2/O2

